

16/0133 – BUCKSTONE FARM, WINDLESHAM ROAD

The extent of the fence, looking east with the gate piers in the distance



The eastern part of the fence (right) where it meets the fence at Laris Farm (left)



16/0133 – BUCKSTONE FARM, WINDLESHAM ROAD

The western part of the fence (left) where it meets the neighbouring fence (right)



View from inside the property showing the old fence still in place behind




16/0133 – BUCKSTONE FARM, WINDLESHAM ROAD

The current view of Buckstone Farm from the road




View of the old fence from 2008





Drawing 2: East of gate elevation - gate pillar proceeding east 6m



Drawing 1 : East of gate elevation - Laris Farm boundary proceeding west  
10m along roadside

